

# DPW Vehicles - 2016

TOWNSHIP OF BYRAM			D - Dump Truck, M - Mason Dump, P - Pickup			NOTES:
Year	Vehicle Make	Vehicle Model	Vehicle #	Mileage	Vin Number	
2001	INTERNATIONAL	2674 ROLLOFF	D1	54,000	1HTGLAET21H376932	Gauges do not work, dumpsters rusted with holes
2015	FREIGHTLINER	108SD	D2	730	1FVAG5CY4FHGL6159	New
1995	INTERNATIONAL	DUMP TRUCK	D3	58,501	1HTSDAAR8SH205668	Truck has rust, rusted under carriage and dump, interior seats are ripped, need of clutch 2016.
1994	INTERNATIONAL	DUMP TRUCK	D4	60,522	1HTSDAARXR601207	Dump body rusted (holes)
1990	INTERNATIONAL	DUMP TRUCK	D5	89,352	1HTSDDBRXL248782	<b>OUT OF SERVICE - SCHEDULED TO BE AUCTIONED</b> Condition of truck poor, body rusted, under carriage rusted, dump rusted, bad rear hubs.
2008	INTERNATIONAL	7400 TRUCK	D7	17,043	1HTWEAAR98J659766	Some Rust
2001	DODGE	3500 Mason Dump	M1	62,000	3B6MF36681M575219	<b>OUT OF SERVICE - SCHEDULED TO BE AUCTIONED</b> Bad transmission, bad rear axles, passenger door screwed shut, fuel tank fell off, cab rust, dump body rusted and will not lift.
2009	Sterling	Bullet	M2	37,000	3F6WK76L19G520005	No issues reported
2009	Sterling	Bullet	M3	43,000	3F6WK76L19G520006	No issues reported
1998	DODGE	3500 Mason Dump	M4	81,000	3B6MF3664WM253605	<b>OUT OF SERVICE - SCHEDULED TO BE AUCTIONED</b> Bad rear differential, dump body rusted and cab rust.
2009	Sterling	Bullet	M5	35,000	3F6WK76L79G521921	No issues reported
2005	FORD	F550 Mason Dump	M6	46,000	1FDAF5745EC96892	Dump body rusted (holes), rebuilt dump body.
2009	Sterling	Bullet	M7	37,000	3F6WK76L09G514356	No issues reported
2012	GMC SIERRA	4WD EXT CAP PICKUP	P1	33,157	1GT522CG6CZ254672	Very Good
2006	FORD	F350 TRUCK	P2	77,639	1FDWFF31P06EA57232	XL Super Duty, 4WD - Rusted body, metal panels replaced with 3/4 plywood, undercarriage rusted out, interior ripped seats, roof of cab rusted
2007	DODGE	3500 TRUCK	P3	52,400	3D6WH46A27G787995	Good, Some frame & component rust.
2006	FORD	F350 TRUCK	P5	85,469	1FDWFF31P96EA57231	XL Super Duty, 4WD - Rusted body, bed of truck rusted replaced by 3/4 plywood, under carriage rusted, interior ripped seats, roof rusted and just fixed with fiberglass.
2004	ELGIN	SWEEPER	SW-02	22,700	49HAADB74DN22266	Replaced mechanical belt and frame 2014, rear body components rusting, Good Shape.
1987	Case	WB14B - Loader	N/A	3,433 hours	9162674	Some rust, breaks, leaks fluid, bushings are bad, trunnion bearings are bad in rear. Battery issues.
2001	New Holland	LW 170 - Loader	N/A	3,316 hours	2EF0LW17000570199	Rust, holes in panels, seat is ripped.
1999	New Holland	555E - Backhoe	N/A	7,700 hours	31020807	Leaking swing cylinder, bushing are worn.

# D1 – 2001 International Rolloff



# D2 – 2015 Freightliner Dump Truck



# D3 – International Dump Truck



# D4 – International Dump Truck



# D5 – International Dump Truck



# D7 – International Dump Truck



# M1 – 3500 Dodge Mason Dump



# M2 – Sterling Bullet



# M3 – Sterling Bullet



# M4 – Dodge 3500 Mason Dump





# M6 – Ford F550 Mason Dump



# M7 – Sterling Bullet




# P1 – GMC Sierra – 4WD Pickup



## P2 – Ford F350



# P3 – Dodge 3500



# P5 – Ford F350



# Elgin Sweeper



# Case Loader



# New Holland Loader



# New Holland Backhoe

